How To Order Flowstream Multigas Series

Select the appropriate symbols to build a model code:

Example: OFM - E F - 3 H 51 - T - X 1B - D10 - R

SERIES = **OFM**

MATERIAL FOR METER BODY

Anodized Aluminum	= **E**
316 Stainless Steel	= **I**

SEALS

Viton	= **F**
Buna N	= **B**

MULTIGAS FLOW SELECTION CHART

SCFH (Air)

Line Size In Inches	Pipe Size Symbol	Nominal Size	SCFH	Max Pressure Drop PSI
1/4	2	H 20	1	2
	2	H 40	4	2
	2	H 41	25	2
	2	H 42	50	2
	2	H 43	75	2
	2	H 44	100	2
	2	H 45	175	2
	2	H 46	200	2
	2	H 47	300	3
	2	H 48	400	3
3/8	3	H 49	300	2
	3	H 50	400	2
	3	H 51	450	2
	3	H 52	500	2
	3	H 53	600	3
	3	H 54	700	3
1/2	4	H 55	500	2
	4	H 56	600	2
	4	H 57	700	2
	4	H 58	800	2
	4	H 59	900	3
	4	H 60	325	3
	4	H 61	350	3
	4	H 63	375	3
	4	H 64	1000	3
	4	H 65	1100	3
	4	H 66	1200	3
3/4	6	H 67	1000	1.4
	6	H 68	1300	1.8
	6	H 69	1350	1.7
	6	H 70	1400	2.1
	6	H 71	1500	2.4
	6	H 72	1550	3
	6	H 73	1600	2.5
	6	H 75	1650	3
	6	H 76	1700	2.7
	6	H 78	1800	2.9
	6	H 79	1900	3.1
	6	H 80	2000	3.3

SLPM (Air)

Line Size In Inches	Pipe Size Symbol	Nominal Size	SCCM	Max Pressure Drop PSI
1/4	2	C 30	500	2
			SLPM	
	2	P 50	2	2
	2	P 51	10	2
	2	P 52	25	2
	2	P 53	50	2
	2	P 54	75	2
	2	P 56	100	2
	2	P 57	150	3
	2	P 58	200	3
3/8	3	P 59	150	2
	3	P 60	200	2
	3	P 64	250	3
	3	P 65	300	3
	3	P 66	350	3
1/2	4	P 67	200	2
	4	P 68	250	2
	4	P 69	300	2
	4	P 70	350	2
	4	P 71	400	2
	4	P 72	450	3
	4	P 74	500	3
	4	P 75	550	3
3/4	6	P 76	500	1.4
	6	P 77	600	1.8
	6	P 79	700	2.4
	6	P 80	800	2.7
	6	P 81	900	3.1
	6	P 82	1000	3.5

THREAD TYPE FOR THREADED PORT

N	= NPT
T	= SAE
B	= BSPT
P	= BSPP

DIGITAL VISUAL DISPLAY WITH OUTPUT

X1A	= 4-20mA
X1B	= 4-20mA with 2 alarms
X2A	= 4-20mA IS
X4A	= 0-5 VDC
X4B	= 0-5 VDC with 2 alarms
X5A	= 0-10 VDC
X5B	= 0-10 VDC with 2 alarms
X12A	= 1-5 VDC
X12B	= 1-5 VDC with 2 alarms
X14A	= 2-10 VDC
X14B	= 2-10 VDC with 2 alarms
X19A	= 0-1000 HZ
X20A	= 200-1200 HZ
X22A	= pulse out (rate varies with size)
X30A	= 0-5 VDC (bi-directional flow)
X40A	= visual readout only battery powered

CABLE LENGTH

3 feet standard	= **D3**
Specify required cable length in feet	= **D__**
No cable (battery powered)	= **B**

SPECIAL OPTIONS

CLEAN FOR OXYGEN SERVICE = **C1**

CALIBRATE ON ACTUAL GAS

Argon	= **R**
Nitrogen	= **N**
Helium	= **HE**
Carbon Dioxide	= **CO2**

NOTE: Consult foactory for other gasses and mixes

CALIBRATE AT SPECIFIC PRESSURE IN PSIA

NOTE: Select any specific pressure between 10 and 100 PSIA

EX: Optimize for 10 PSIA pressure	= **P10**
Optimize for 45 PSIA pressure	= **P45**

VACUUM USE (7.35 to 14.7PSIA) = **ZVAC**

NOTE: Also good for use at normal pressures

GAS SIZING FACTORS

Gas Number	Gas	Multiplier	Accuracy Degredation (+/-)
1	Air	1.00	0.0%
2	Argon	0.82	0.2%
3	CO2	0.61	1.0%
4	Helium	0.92	1.0%
5	Hydrogen	2.05	0.0%
6	Methane	1.65	0.5%
7	Nitrogen	1.03	0.0%
8	Oxygen	0.90	0.5%

For example, selection of a nominal flow size 3M15 would read to a maximum of 300 SCFH of air and would also read to 247 SCFH Argon with additional inaccuracy or .2%

NOTE: These multipliers are to help size and choose the appropriate flow meter. Each gas is displayed directly on the flow meter.

How To Order Flowstream for a Single Gas

Select the appropriate symbols to build a model code:

Example: OFS - E F - 3 A 200 SLPM - T - X 1B - D10 - R

SERIES = OFS

MATERIAL FOR METER BODY

Anodized Aluminum	= E
316 Stainless Steel	= I

SEALS

Viton	= F
Buna N	= B

THREAD TYPE FOR THREADED PORT

N	= NPT
T	= SAE
B	= BSPT
P	= BSPP

GAS

Air	Acetylene	Argon	CO	CO2	Helium	Hydrogen	MAPP GAS	Methane	Nitrogen	Nitrous Oxide	Oxygen
= A	= AC	= R	= CO	= CO2	= HE	= H	= MG	= M	= N	= NO	= O2

PIPE SIZE in Inches		MAXIMUM FLOW IN SLPM											
1/4	= 2	128	256	107	128	64	116	256	256	107	128	160	116
3/8	= 3	* 228	457	190	228	114	208	457	457	190	228	286	208
1/2	= 4	548	1096	457	548	274	498	1096	1096	457	548	685	498
3/4	= 6	1000	1999	833	1000	500	909	1999	1999	833	1000	1250	909
		MAXIMUM FLOW IN SCFH											
1/4	= 2	280	560	233	280	140	255	560	560	233	280	350	255
3/8	= 3	500	1000	417	500	250	455	1000	1000	417	500	625	455
1/2	= 4	1200	2400	1000	1200	600	1091	2400	2400	1000	1200	1500	1091
3/4	= 6	2188	4377	1824	2188	1094	1989	4377	4377	1824	2188	2736	1989

NOTE: Lowest maximum flow rates are 50 SCCM and 1 SCFH respectively.

** NOTE: The flows selected in each size must be less than or equal to the maximum.*

OUTPUT

Digital Visual Display with Output

X 1A	= 4-20mA
X 1B	= 4-20mA with 2 alarms
X 2A	= 4-20mA Intrinsically Safe
X 4A	= 0-5 VDC
X 4B	= 0-5 VDC with 2 alarms
X 5A	= 0-10 VDC
X 5B	= 0-10 VDC with 2 alarms
X 12A	= 1-5 VDC
X 12B	= 1-5 VDC with 2 alarms
X 14A	= 2-10 VDC
X 14B	= 2-10 VDC with 2 alarms
X 19A	= 0-1000 HZ
X 20A	= 200-1200 HZ
X 22A	= pulse out (rate varies with size)
X 30A	= 0-5 VDC (bi-directional flow)
X 40A	= visual readout only (battery powered)

No Visual Display with Output

Z 1A	= 4-20mA
Z 2A	= 4-20mA Intrinsically Safe
Z 4A	= 0-5 VDC
Z 5A	= 0-10 VDC
Z 12A	= 1-5 VDC
Z 14A	= 2-10 VDC
Z 19A	= 0-1000 HZ
Z 20A	= 200-1200 HZ
Z 22A	= pulse out (rate varies with size)
Z 30A	= 0-5 VDC (bi-directional flow)

CABLE LENGTH

3 feet standard	= D3
Specify required cable length in feet	= D__
No cable (battery powered)	= B

SPECIAL OPTIONS

CLEAN FOR OXYGEN SERVICE = C1

CALIBRATE ON ACTUAL GAS

Argon	= R
Nitrogen	= N
Helium	= HE
Carbon Dioxide	= CO2

NOTE: Consult factory for other gasses and mixes

CALIBRATE AT SPECIFIC PRESSURE IN PSIA

NOTE: Select any specific pressure between 10 and 100 PSIA

EX: Optimize for 10 PSIA pressure = P10
Optimize for 45 PSIA pressure = P45

VACUUM USE (7.35 to 14.7PSIA) = ZVAC

NOTE: Also good for use at normal pressures